



State of New Jersey  
Department of Community Affairs  
Division of Codes and Standards  
Bureau of Housing Inspection

**INSPECTION REPORT AND ORDERS OF THE COMMISSIONER**

**Registration #:** 1915023375  
**Notice #:** 29337625  
**Issuance Date:** October 01, 2018  
**Inspector(s):** DEBORAH STECKLER

**Inspection Type:** Cyclical  
**Inspection Date:** 08/28/2018  
**Re-inspection Date:** On or after 11/30/2018

**Owner Information:** BROOKSIDE REALTY URBAN RENEWAL  
LLC  
C/O MICHAEL WIEDER  
691 ELIZABETH AVENUE  
#2  
Newark, NJ 07112  
9732821100x5012

**Property Information:** 33 MILL STREET  
33 MILL Street  
Newton Town, Sussex County

**Property Type:** Multiple Dwelling  
**Buildings:** 3  
**Apartments:** 0  
**Dwelling Units:** 221  
**Total Units:** 221

Please take notice that the Inspections conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that violations listed below exist at said premises in contravention of the Hotel Multiple Dwelling Law and of the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated there under. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76) as amended and supplemented; N.J.S.A. 55:13A-1 et seq.

Lt. Governor  
Sheila Y. Oliver,  
Commissioner, Community Affairs

A handwritten signature in black ink, appearing to read "Edwin Tomkiewicz".

By: Edwin Tomkiewicz, Chief, Bureau of Housing Inspection

**ATTENTION - PLEASE READ FURTHER INSTRUCTIONS AT END OF REPORT**

## **OPEN VIOLATIONS**

PLEASE REFER TO THE PERMIT INFORMATION AT THE END OF THIS REPORT FOR CORRECTIVE ACTIONS WITH A FOOTNOTE OF a "P" or "M". ANY VIOLATION CITED IN THIS REPORT SHALL BE CORRECTED AND SHALL BE MAINTAINED AND/OR KEPT IN AN OPERATIVE CONDITION AT ALL TIMES PURSUANT TO N.J.A.C. 5:10-1.6 AND/OR N.J.A.C. 5:70 ET SEQ.

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900869	Building 1 33 MILL Street	Building Exterior 1 -	Balcony-2A	SECURE LOOSE Guardrail's [N.J.A.C. 5:10-7.7(b)]	Y
3900866	Building 1 33 MILL Street	Building Exterior 1 -	Balcony-remove bees/hornets from balconies	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N
3900867	Building 1 33 MILL Street	Building Exterior 1 -	Balcony-remove bees/hornets from balconies	Maintain building in in a condition free from infestation [N.J.A.C. 5:10-10.2(a)]	N
3900871	Building 1 33 MILL Street	Building Exterior 1 -	Entire Building	Caulk window frames to prevent the penetration of moisture or infestation [N.J.A.C. 5:10-7.4]	N
3900870	Building 1 33 MILL Street	Building Exterior 1 -	Entire Building-where leaking	REPAIR ROOF [N.J.A.C. 5:10-7.4]	N
3900868	Building 1 33 MILL Street	Building Exterior 1 -	Entire Building-where needed including 7A,7U,7V,5V,4Q,2A,2B	Repair balcony *M [N.J.A.C. 5:10-7.3(a)]	N
3900966	Building 1 33 MILL Street	Building Common 1 -	Elevator-Elevator 2 Side	Maintain in each elevator a mirror that will enable persons, prior to entering into such elevator, to view the inside thereof to determine whether any person is in such elevator [N.J.A.C. 5:10-12.4]	N
3900965	Building 1 33 MILL Street	Building Common 1 -	Elevator-Elevator1 Front	Maintain in each elevator a mirror that will enable persons, prior to entering into such elevator, to view the inside thereof to determine whether any person is in such elevator [N.J.A.C. 5:10-12.4]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900865	Building 1 33 MILL Street	Building 1 - Common	Entire Building-all hall vents into units without fire damper	Provide fire rated transom/window with material consistent with corridor material *M [N.J.A.C. 5:70-4.11(o)]	Y
3900846	Building 1 33 MILL Street	Building 1 - Common	Entire Building-fan&clean repair ductwork all units/all levels	REPAIR OR REPLACE MECHANICAL BATHROOM VENTILATION TO EXHAUST AT LEAST 40 CUBIC FEET OF AIR PER MINUTE PER URINAL OR TOILET *M [N.J.A.C. 5:10-16.3(a)4]	N
3900845	Building 1 33 MILL Street	Building 1 - Common	Entire Building-fan&clean repair ductwork all units/all levels	REPAIR OR REPLACE KITCHEN VENTILATION EXHAUST SYSTEM TO EXHAUST AT LEAST 2 CUBIC FEET OF AIR PER MINUTE PER SQUARE FOOT OF FLOOR AREA DIRECTLY TO THE OUTSIDE. *M [N.J.A.C. 5:10-16.3(a)1]	N
3900848	Building 1 33 MILL Street	Building 1 - Common	Hallway-10 N-R	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900852	Building 1 33 MILL Street	Building 1 - Common	Hallway-10W-J	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900851	Building 1 33 MILL Street	Building 1 - Common	Hallway-2A-E	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900850	Building 1 33 MILL Street	Building 1 - Common	Hallway-3M-Q	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900849	Building 1 33 MILL Street	Building 1 - Common	Hallway-5 D-E	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900859	Building 1 33 MILL Street	Building 1 - Common	Hallway-5N-Q	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900862	Building 1 33 MILL Street	Building 1 - Common	Hallway-6M-Q	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900858	Building 1 33 MILL Street	Building 1 - Common	Hallway-6N-Q	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900861	Building 1 33 MILL Street	Building 1 - Common	Hallway-6Y-W	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900857	Building 1 33 MILL Street	Building 1 - Common	Hallway-6Y-W	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900856	Building 1 33 MILL Street	Building 1 - Common	Hallway-8A-D	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900854	Building 1 33 MILL Street	Building 1 - Common	Hallway-8N-S	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900855	Building 1 33 MILL Street	Building 1 - Common	Hallway-8W-J	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900853	Building 1 33 MILL Street	Building 1 - Common	Hallway-9N-Q	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900860	Building 1 33 MILL Street	Building 1 - Common	Hallway-near 9N	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900864	Building 1 33 MILL Street	Building 1 - Common	Lobby	Keep posted at all times, in a conspicuous location on the premises, a copy of the current certificate of inspection issued pursuant to the Uniform Fire Safety Act for a building subject to the Act, that is deemed a life hazard use pursuant to N.J.A.C. 5:70-2.4 through 2.4D [N.J.A.C. 5:10-1.12(e)2]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900863	Building 1 33 MILL Street	Building 1 - Common	Stairwell/Stairway- flr1-2 nearE	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900847	Building 1 33 MILL Street	Building 1 - Common	side door lower level repair intercom system	Repair or replace door latch release system. [N.J.A.C. 5:10-19.2(a)8]	N
3899961	Building 1 33 MILL Street	Unit 1A, Floor 1, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899962	Building 1 33 MILL Street	Unit 1A, Floor 1, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900236	Building 1 33 MILL Street	Unit 1A, Floor 1, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899964	Building 1 33 MILL Street	Unit 1B, Floor 1, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899963	Building 1 33 MILL Street	Unit 1B, Floor 1, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900237	Building 1 33 MILL Street	Unit 1B, Floor 1, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900318	Building 1 33 MILL Street	Unit 1B, Floor 1, Building 1	Kitchen	Occupants shall place storage in a manner as to not create a hazard [N.J.A.C. 5:10-5.1(d)]	N
3900317	Building 1 33 MILL Street	Unit 1B, Floor 1, Building 1	Kitchen	Secure kitchen cabinet to wall [N.J.A.C. 5:10-20.1(a)7]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899965	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899966	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900238	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900319	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Living Room-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900321	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Living Room-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900320	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Living Room-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900322	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Living Room-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900324	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900325	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N
3900323	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N
3900326	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900327	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900328	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900329	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3899967	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899968	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900239	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899971	Building 1 33 MILL Street	Unit 1E, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899972	Building 1 33 MILL Street	Unit 1E, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900241	Building 1 33 MILL Street	Unit 1E, Floor 1, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900330	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900333	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom-bedroom 1	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900335	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom-bedroom 1	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900337	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom-bedroom 1	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900331	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom-bedroom 1	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900334	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom-bedroom 2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900336	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom-bedroom 2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900338	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom-bedroom 2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900332	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom-bedroom 2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3899974	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899973	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900242	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899970	Building 1 33 MILL Street	Unit 10A, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899969	Building 1 33 MILL Street	Unit 10A, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900240	Building 1 33 MILL Street	Unit 10A, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900767	Building 1 33 MILL Street	Unit 10A, Floor 10, Building 1	Front Door	Provide for every unit of dwelling space in hotels and multiple dwellings some permanent and legible identification by letter, number or other symbol at or near the front entrance thereof [N.J.A.C. 5:10-18.2(a)]	N
3900768	Building 1 33 MILL Street	Unit 10A, Floor 10, Building 1	Hallway-closet	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3899992	Building 1 33 MILL Street	Unit 10B, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899991	Building 1 33 MILL Street	Unit 10B, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900251	Building 1 33 MILL Street	Unit 10B, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900769	Building 1 33 MILL Street	Unit 10C, Floor 10, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900014	Building 1 33 MILL Street	Unit 10C, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900013	Building 1 33 MILL Street	Unit 10C, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900262	Building 1 33 MILL Street	Unit 10C, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900770	Building 1 33 MILL Street	Unit 10C, Floor 10, Building 1	Hallway-closet near bathroom	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900771	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Bedroom-BR1-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900773	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Bedroom-BR1-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900772	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Bedroom-BR2-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900774	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Bedroom-BR2-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900035	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900036	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900273	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900780	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bathroom	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N
3900775	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bedroom-BR1- remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900777	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bedroom-BR1- remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900779	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bedroom-BR2	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900778	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bedroom-BR2- remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900776	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bedroom-BR2- remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900057	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900058	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900284	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900782	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900781	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Bathroom-repair tub drain/plug	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N
3900079	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900080	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900295	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900783	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Kitchen-sink drain	Repair or replace kitchen sink sanitary disposal or sewer system*M [N.J.A.C. 5:10-20.1(a)1]	N
3900102	Building 1 33 MILL Street	Unit 10G, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900101	Building 1 33 MILL Street	Unit 10G, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900306	Building 1 33 MILL Street	Unit 10G, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900784	Building 1 33 MILL Street	Unit 10G, Floor 10, Building 1	Kitchen-pantry/closet door	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3899735	Building 1 33 MILL Street	Unit 10H, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899736	Building 1 33 MILL Street	Unit 10H, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900123	Building 1 33 MILL Street	Unit 10H, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899757	Building 1 33 MILL Street	Unit 10J, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899758	Building 1 33 MILL Street	Unit 10J, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900134	Building 1 33 MILL Street	Unit 10J, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900787	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Bedroom-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900788	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Bedroom-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900786	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Bedroom-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900785	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Bedroom-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3899780	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899779	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900145	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900794	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900793	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bathroom-sink/basin	Repair or replace faucet *M [N.J.A.C. 5:10-21.1(e)]	N
3900791	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bedroom-repair leak then repair & paint all	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900792	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bedroom-repair leak then repair & paint all	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900790	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bedroom-repair leak then repair & paint all	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900789	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bedroom-repair leak then repair & paint all	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3899802	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899801	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900156	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900798	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Living Room-repair leak then repair & paint all	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900797	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Living Room-repair leak then repair & paint all	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900796	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Living Room-repair leak then repair & paint all	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900795	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Living Room-repair leak then repair & paint all	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900799	Building 1 33 MILL Street	Unit 10M, Floor 10, Building 1	Entire Unit	Do not operate portable, electric space heaters within 3 feet (914 mm) of combustible materials or in locations for which they are not listed [N.J.A.C. 5:70-3,605.10.4]	Y
3899823	Building 1 33 MILL Street	Unit 10M, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899824	Building 1 33 MILL Street	Unit 10M, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900167	Building 1 33 MILL Street	Unit 10M, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899846	Building 1 33 MILL Street	Unit 10N, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899845	Building 1 33 MILL Street	Unit 10N, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900178	Building 1 33 MILL Street	Unit 10N, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900800	Building 1 33 MILL Street	Unit 10N, Floor 10, Building 1	Kitchen	Repair or replace kitchen cabinets, cabinet doors or drawers to open and close properly. [N.J.A.C. 5:10-20.1(a)7]	N
3900802	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900803	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900801	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3899868	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899867	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900189	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899889	Building 1 33 MILL Street	Unit 10Q, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899890	Building 1 33 MILL Street	Unit 10Q, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900200	Building 1 33 MILL Street	Unit 10Q, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899911	Building 1 33 MILL Street	Unit 10R, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899912	Building 1 33 MILL Street	Unit 10R, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900211	Building 1 33 MILL Street	Unit 10R, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900805	Building 1 33 MILL Street	Unit 10S, Floor 10, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900804	Building 1 33 MILL Street	Unit 10S, Floor 10, Building 1	Bathroom-sink/basin	Repair or replace faucet *M [N.J.A.C. 5:10-21.1(e)]	N
3899933	Building 1 33 MILL Street	Unit 10S, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899934	Building 1 33 MILL Street	Unit 10S, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900222	Building 1 33 MILL Street	Unit 10S, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900807	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Entire Unit	Refrain from passing extension cord across any path of travel [N.J.A.C. 5:10-13.1(d)4]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900808	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Entire Unit	Extension cords must not be used in place of permanent wiring. *M [N.J.A.C. 5:70-3,605.5]	Y
3899949	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899950	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900230	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900806	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Kitchen	REPAIR FLOOR COVERING to be free of hazards. [N.J.A.C. 5:10-8.2(a)]	N
3899951	Building 1 33 MILL Street	Unit 10U, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899952	Building 1 33 MILL Street	Unit 10U, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900231	Building 1 33 MILL Street	Unit 10U, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900814	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900810	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900816	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900812	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899954	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899953	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900232	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900815	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900813	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900809	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900811	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900825	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR1	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900829	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR1	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900821	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR1	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900817	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR1	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900818	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900826	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900833	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR2	Repair or replace electric outlet. [N.J.A.C. 5:10-13.1(b)7]	N
3900830	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900822	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899956	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899955	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900233	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900828	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Hallway	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900824	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Hallway	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900820	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Hallway	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900832	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Hallway	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900823	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900831	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900819	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900827	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900840	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR1- remove water damaged substrate before repair	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900838	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR1- remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900836	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR1- remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900834	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR1- remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900835	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR2- remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900837	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR2- remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900841	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR2- remove water damaged substrate before repair	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900839	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR2- remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899957	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899958	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900234	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900843	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Kitchen	Repair or replace refrigerator to maintain temperatures between 32 and 50 degrees to avoid food spoilage. [N.J.A.C. 5:10-20.1(a)5]	N
3900842	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Kitchen-stove/oven	Repair or replace cooking facility which is safely connected to a sufficient capacity electrical system or if gas connected to permanent fixtures and tubing to avoid the leakage of gas. *M [N.J.A.C. 5:10-20.1(a)6]	N
3900844	Building 1 33 MILL Street	Unit 10Y, Floor 10, Building 1	Entire Unit	Provide admission to dwelling unit to conduct inspection. [N.J.A.C. 5:10-1.10(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899959	Building 1 33 MILL Street	Unit 10Y, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899960	Building 1 33 MILL Street	Unit 10Y, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900235	Building 1 33 MILL Street	Unit 10Y, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900347	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Bathroom-repair leak then repair ceiling tile	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900339	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900343	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900341	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900345	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3899975	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899976	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900243	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900342	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900340	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900344	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900346	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3899978	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899977	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900244	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900350	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900348	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900349	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900351	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900356	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Bathroom-repair leak then repair ceiling tile	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899980	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899979	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900245	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900352	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900353	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900354	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900355	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900361	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom-Bedroom 1	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900367	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom-Bedroom 1	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900364	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom-Bedroom 1	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900358	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom-Bedroom 1	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900368	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom-Bedroom 2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900359	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom-Bedroom 2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900365	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom-Bedroom 2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900362	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom-Bedroom 2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899982	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899981	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900246	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900360	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900366	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900363	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900357	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900374	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N
3900373	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N
3900375	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899983	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899984	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900247	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900372	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900371	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900370	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900369	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900382	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 1	Repair woodwork to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900376	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 1	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900385	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 1	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900379	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 1	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900380	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900386	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900383	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	Repair woodwork to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900377	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900389	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	Replace broken glass [N.J.A.C. 5:10-7.3(c)]	N
3900390	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	repair windows [N.J.A.C. 5:10-7.4]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900388	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	REPLACE FLOOR COVERING to be free of hazards. [N.J.A.C. 5:10-8.2(a)]	N
3899986	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899985	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900248	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900381	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900387	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900378	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900384	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Living Room	Repair woodwork to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899988	Building 1 33 MILL Street	Unit 3A, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899987	Building 1 33 MILL Street	Unit 3A, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900249	Building 1 33 MILL Street	Unit 3A, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900391	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900393	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900397	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900395	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899990	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899989	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900250	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900396	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900398	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900392	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900394	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900400	Building 1 33 MILL Street	Unit 3C, Floor 3, Building 1	Bathroom	Repair or replace electric light fixture. [N.J.A.C. 5:10-13.1(b)7]	N
3899993	Building 1 33 MILL Street	Unit 3C, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899994	Building 1 33 MILL Street	Unit 3C, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900252	Building 1 33 MILL Street	Unit 3C, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900399	Building 1 33 MILL Street	Unit 3C, Floor 3, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3900405	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900403	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900415	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900404	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900402	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900412	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 1-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900410	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 1-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900406	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 1-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900408	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 1-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900407	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 2- repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900411	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 2- repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900413	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 2- repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900409	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 2- repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899995	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899996	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900253	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900414	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Front Door	Install chain guard on entry door(s). [N.J.A.C. 5:10-19.2(a)5]	N
3900401	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3900416	Building 1 33 MILL Street	Unit 3E, Floor 3, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899998	Building 1 33 MILL Street	Unit 3E, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899997	Building 1 33 MILL Street	Unit 3E, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900254	Building 1 33 MILL Street	Unit 3E, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900000	Building 1 33 MILL Street	Unit 3F, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899999	Building 1 33 MILL Street	Unit 3F, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900255	Building 1 33 MILL Street	Unit 3F, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900001	Building 1 33 MILL Street	Unit 3G, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900002	Building 1 33 MILL Street	Unit 3G, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900256	Building 1 33 MILL Street	Unit 3G, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900003	Building 1 33 MILL Street	Unit 3H, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900004	Building 1 33 MILL Street	Unit 3H, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900257	Building 1 33 MILL Street	Unit 3H, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900005	Building 1 33 MILL Street	Unit 3J, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900006	Building 1 33 MILL Street	Unit 3J, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900258	Building 1 33 MILL Street	Unit 3J, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900007	Building 1 33 MILL Street	Unit 3K, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900008	Building 1 33 MILL Street	Unit 3K, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900259	Building 1 33 MILL Street	Unit 3K, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900009	Building 1 33 MILL Street	Unit 3L, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900010	Building 1 33 MILL Street	Unit 3L, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900260	Building 1 33 MILL Street	Unit 3L, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900012	Building 1 33 MILL Street	Unit 3M, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900011	Building 1 33 MILL Street	Unit 3M, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900261	Building 1 33 MILL Street	Unit 3M, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900419	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900417	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900016	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900015	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900263	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900420	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900418	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900421	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Bathroom-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900425	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Bathroom-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900427	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Bathroom-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900423	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Bathroom-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900429	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N
3900018	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900017	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900264	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900428	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Living Room-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900426	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Living Room-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900424	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Living Room-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900422	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Living Room-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900433	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900432	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900430	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900431	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900434	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Bedroom-BR 1	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900019	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900020	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900265	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900438	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900437	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900435	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900436	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900021	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900022	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900266	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900442	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900441	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900439	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900440	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900443	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900024	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900023	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900267	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900025	Building 1 33 MILL Street	Unit 3V, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900026	Building 1 33 MILL Street	Unit 3V, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900268	Building 1 33 MILL Street	Unit 3V, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900447	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900446	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900448	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Bathroom	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N
3900444	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900445	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900027	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900028	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900269	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900029	Building 1 33 MILL Street	Unit 3X, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900030	Building 1 33 MILL Street	Unit 3X, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900270	Building 1 33 MILL Street	Unit 3X, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900449	Building 1 33 MILL Street	Unit 3X, Floor 3, Building 1	Kitchen	Repair or replace refrigerator to maintain temperatures between 32 and 50 degrees to avoid food spoilage. [N.J.A.C. 5:10-20.1(a)5]	N
3900032	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900031	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900271	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900453	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900451	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900450	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900452	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900458	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Bathroom-sink/basin	Repair or replace faucet *M [N.J.A.C. 5:10-21.1(e)]	N
3900456	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Bedroom-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900455	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Bedroom-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900454	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Bedroom-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900457	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Bedroom-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900034	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900033	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900272	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900459	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Living Room-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900460	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Living Room-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900462	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Living Room-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900461	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Living Room-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900037	Building 1 33 MILL Street	Unit 4B, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900038	Building 1 33 MILL Street	Unit 4B, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900274	Building 1 33 MILL Street	Unit 4B, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900463	Building 1 33 MILL Street	Unit 4B, Floor 4, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3900040	Building 1 33 MILL Street	Unit 4C, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900039	Building 1 33 MILL Street	Unit 4C, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900275	Building 1 33 MILL Street	Unit 4C, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900041	Building 1 33 MILL Street	Unit 4D, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900042	Building 1 33 MILL Street	Unit 4D, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900276	Building 1 33 MILL Street	Unit 4D, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900468	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900464	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900466	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900470	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900044	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900043	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900277	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900467	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900471	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900465	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900469	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900046	Building 1 33 MILL Street	Unit 4F, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900045	Building 1 33 MILL Street	Unit 4F, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900278	Building 1 33 MILL Street	Unit 4F, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900472	Building 1 33 MILL Street	Unit 4F, Floor 4, Building 1	Kitchen	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N
3900047	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900048	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900279	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900475	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Hallway	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900473	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Hallway	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900477	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Hallway	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900479	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Hallway	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900480	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900476	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900474	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900478	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900049	Building 1 33 MILL Street	Unit 4H, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900050	Building 1 33 MILL Street	Unit 4H, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900280	Building 1 33 MILL Street	Unit 4H, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900483	Building 1 33 MILL Street	Unit 4J, Floor 4, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N
3900484	Building 1 33 MILL Street	Unit 4J, Floor 4, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900052	Building 1 33 MILL Street	Unit 4J, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900051	Building 1 33 MILL Street	Unit 4J, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900281	Building 1 33 MILL Street	Unit 4J, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900481	Building 1 33 MILL Street	Unit 4K, Floor 4, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N
3900482	Building 1 33 MILL Street	Unit 4K, Floor 4, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900054	Building 1 33 MILL Street	Unit 4K, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900053	Building 1 33 MILL Street	Unit 4K, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900282	Building 1 33 MILL Street	Unit 4K, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900485	Building 1 33 MILL Street	Unit 4L, Floor 4, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900056	Building 1 33 MILL Street	Unit 4L, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900055	Building 1 33 MILL Street	Unit 4L, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900283	Building 1 33 MILL Street	Unit 4L, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900491	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Bathroom-shower head & faucet	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900486	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900487	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900488	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900489	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900060	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900059	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900285	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900490	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit-repair windws to readily open&close	repair windows [N.J.A.C. 5:10-7.4]	N
3900492	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Front Door	Install chain guard on entry door(s). [N.J.A.C. 5:10-19.2(a)5]	N
3900061	Building 1 33 MILL Street	Unit 4N, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900062	Building 1 33 MILL Street	Unit 4N, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900286	Building 1 33 MILL Street	Unit 4N, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900493	Building 1 33 MILL Street	Unit 4N, Floor 4, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3900494	Building 1 33 MILL Street	Unit 4P, Floor 4, Building 1	Bathroom	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900064	Building 1 33 MILL Street	Unit 4P, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900063	Building 1 33 MILL Street	Unit 4P, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900287	Building 1 33 MILL Street	Unit 4P, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900065	Building 1 33 MILL Street	Unit 4Q, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900066	Building 1 33 MILL Street	Unit 4Q, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900288	Building 1 33 MILL Street	Unit 4Q, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900495	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900496	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900497	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900498	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900499	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N
3900067	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900068	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900289	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900069	Building 1 33 MILL Street	Unit 4S, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900070	Building 1 33 MILL Street	Unit 4S, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900290	Building 1 33 MILL Street	Unit 4S, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900071	Building 1 33 MILL Street	Unit 4T, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900072	Building 1 33 MILL Street	Unit 4T, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900291	Building 1 33 MILL Street	Unit 4T, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900500	Building 1 33 MILL Street	Unit 4U, Floor 4, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900073	Building 1 33 MILL Street	Unit 4U, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900074	Building 1 33 MILL Street	Unit 4U, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900292	Building 1 33 MILL Street	Unit 4U, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900501	Building 1 33 MILL Street	Unit 4U, Floor 4, Building 1	Kitchen-stove/oven	Repair or replace cooking facility which is safely connected to a sufficient capacity electrical system or if gas connected to permanent fixtures and tubing to avoid the leakage of gas. *M [N.J.A.C. 5:10-20.1(a)6]	N
3900502	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900503	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900504	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900505	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900075	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900076	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900293	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900508	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900509	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900507	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900506	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900078	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900077	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900294	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900510	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Front Door	Install chain guard on entry door(s). [N.J.A.C. 5:10-19.2(a)5]	N
3900511	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900515	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900517	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900513	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900519	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Bedroom-closet door BR-2	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900081	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900082	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900296	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900518	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900514	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900512	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900516	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900520	Building 1 33 MILL Street	Unit 4Y, Floor 4, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900084	Building 1 33 MILL Street	Unit 4Y, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900083	Building 1 33 MILL Street	Unit 4Y, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900297	Building 1 33 MILL Street	Unit 4Y, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900521	Building 1 33 MILL Street	Unit 5A, Floor 5, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N
3900086	Building 1 33 MILL Street	Unit 5A, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900085	Building 1 33 MILL Street	Unit 5A, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900298	Building 1 33 MILL Street	Unit 5A, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900087	Building 1 33 MILL Street	Unit 5B, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900088	Building 1 33 MILL Street	Unit 5B, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900299	Building 1 33 MILL Street	Unit 5B, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900089	Building 1 33 MILL Street	Unit 5C, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900090	Building 1 33 MILL Street	Unit 5C, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900300	Building 1 33 MILL Street	Unit 5C, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900522	Building 1 33 MILL Street	Unit 5D, Floor 5, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900091	Building 1 33 MILL Street	Unit 5D, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900092	Building 1 33 MILL Street	Unit 5D, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900301	Building 1 33 MILL Street	Unit 5D, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900093	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900094	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900302	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900525	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900523	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900524	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900526	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900527	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Hallway	Install, at the request of a tenant of a unit in building of Use Group R-2 in which a person who is deaf or hearing-impaired resides, a visual alarm type smoke detector for that unit or, in the case of a rooming or boarding house resident, for that resident's sleeping area *M [N.J.A.C. 5:70-4.9(a)3vii]	Y
3900528	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Hallway	Provide and install a visual alarm type carbon monoxide detector for unit, at request of tenant of a multiple dwelling unit in which a person who is deaf or hearing-impaired resides *M [N.J.A.C. 5:10-28.1(c)]	Y



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900096	Building 1 33 MILL Street	Unit 5F, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900095	Building 1 33 MILL Street	Unit 5F, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900303	Building 1 33 MILL Street	Unit 5F, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900097	Building 1 33 MILL Street	Unit 5G, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900098	Building 1 33 MILL Street	Unit 5G, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900304	Building 1 33 MILL Street	Unit 5G, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900100	Building 1 33 MILL Street	Unit 5H, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900099	Building 1 33 MILL Street	Unit 5H, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900305	Building 1 33 MILL Street	Unit 5H, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900104	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900103	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900307	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900532	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900529	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900530	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900531	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900106	Building 1 33 MILL Street	Unit 5K, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900105	Building 1 33 MILL Street	Unit 5K, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900308	Building 1 33 MILL Street	Unit 5K, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900108	Building 1 33 MILL Street	Unit 5L, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900107	Building 1 33 MILL Street	Unit 5L, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900309	Building 1 33 MILL Street	Unit 5L, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900535	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900110	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900109	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900310	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900533	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Front Door	Replace apartment entry door so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900534	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Front Door	Repair apartment entry door(s) so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900536	Building 1 33 MILL Street	Unit 5N, Floor 5, Building 1	Bathroom	Repair or replace wash basin. *M [N.J.A.C. 5:10-21.1(e)1]	N
3900111	Building 1 33 MILL Street	Unit 5N, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900112	Building 1 33 MILL Street	Unit 5N, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900311	Building 1 33 MILL Street	Unit 5N, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900537	Building 1 33 MILL Street	Unit 5N, Floor 5, Building 1	Stairwell/Stairway	Occupants shall place all garbage within receptacles provided to avoid unsanitary conditions [N.J.A.C. 5:10-5.4(a)]	N
3900114	Building 1 33 MILL Street	Unit 5P, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900113	Building 1 33 MILL Street	Unit 5P, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900312	Building 1 33 MILL Street	Unit 5P, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900546	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900543	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bathroom-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900539	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bathroom-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900545	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bathroom-remove water damaged substrate before repair	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900541	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bathroom-remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900544	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bedroom-remove water damaged substrate before repair	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900542	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bedroom-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900538	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bedroom-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900540	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bedroom-remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900115	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900116	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900313	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900117	Building 1 33 MILL Street	Unit 5R, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900118	Building 1 33 MILL Street	Unit 5R, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900314	Building 1 33 MILL Street	Unit 5R, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900547	Building 1 33 MILL Street	Unit 5R, Floor 5, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3900548	Building 1 33 MILL Street	Unit 5S, Floor 5, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900119	Building 1 33 MILL Street	Unit 5S, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900120	Building 1 33 MILL Street	Unit 5S, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900315	Building 1 33 MILL Street	Unit 5S, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900121	Building 1 33 MILL Street	Unit 5T, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900122	Building 1 33 MILL Street	Unit 5T, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900316	Building 1 33 MILL Street	Unit 5T, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900550	Building 1 33 MILL Street	Unit 5U, Floor 5, Building 1	Bathroom	Repair or replace wash basin drain pipe in bathroom [N.J.A.C. 5:10-21.1(e)1]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900549	Building 1 33 MILL Street	Unit 5U, Floor 5, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899738	Building 1 33 MILL Street	Unit 5U, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899737	Building 1 33 MILL Street	Unit 5U, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900124	Building 1 33 MILL Street	Unit 5U, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899739	Building 1 33 MILL Street	Unit 5V, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899740	Building 1 33 MILL Street	Unit 5V, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900125	Building 1 33 MILL Street	Unit 5V, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899741	Building 1 33 MILL Street	Unit 5W, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899742	Building 1 33 MILL Street	Unit 5W, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900126	Building 1 33 MILL Street	Unit 5W, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900551	Building 1 33 MILL Street	Unit 5W, Floor 5, Building 1	Kitchen-repair freezer	Repair or replace refrigerator to maintain temperatures between 32 and 50 degrees to avoid food spoilage. [N.J.A.C. 5:10-20.1(a)5]	N
3900552	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Bathroom	Repair or replace plumbing fixture waste piping as required *M [N.J.A.C. 5:10-21.1(e)]	N
3900553	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Bathroom-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900556	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Bathroom-remove water damaged substrate before repair	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900555	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Bathroom-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900554	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Bathroom-remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899743	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899744	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900127	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900560	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900559	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900558	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900557	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899745	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899746	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900128	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900561	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Front Door	Repair apartment entry door(s) so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3899747	Building 1 33 MILL Street	Unit 6A, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899748	Building 1 33 MILL Street	Unit 6A, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900129	Building 1 33 MILL Street	Unit 6A, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900562	Building 1 33 MILL Street	Unit 6B, Floor 6, Building 1	Entire Unit	Provide admission to dwelling unit to conduct inspection. [N.J.A.C. 5:10-1.10(a)]	N
3899749	Building 1 33 MILL Street	Unit 6B, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899750	Building 1 33 MILL Street	Unit 6B, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900130	Building 1 33 MILL Street	Unit 6B, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899751	Building 1 33 MILL Street	Unit 6C, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899752	Building 1 33 MILL Street	Unit 6C, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900131	Building 1 33 MILL Street	Unit 6C, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900563	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Bedroom-BR 2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900565	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Bedroom-BR 2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900567	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Bedroom-BR 2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900569	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Entire Unit	Eliminate Nuisance Oder which shall constitute a nuisance that is harmful or potentially harmful to the health and well-being of persons of ordinary sensitivity occupying or using the premises. [N.J.A.C. 5:10-6.2]	N
3899753	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899754	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900132	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900564	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900566	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900568	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900583	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900579	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900575	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900571	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900580	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900576	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900572	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900584	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3899755	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899756	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900133	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900582	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Kitchen	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900570	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Kitchen	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900574	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Kitchen	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900578	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Kitchen	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900581	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900577	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900573	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900585	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3899759	Building 1 33 MILL Street	Unit 6F, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899760	Building 1 33 MILL Street	Unit 6F, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900135	Building 1 33 MILL Street	Unit 6F, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899761	Building 1 33 MILL Street	Unit 6G, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899762	Building 1 33 MILL Street	Unit 6G, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900136	Building 1 33 MILL Street	Unit 6G, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900587	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900589	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900588	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900586	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3899764	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899763	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900137	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900590	Building 1 33 MILL Street	Unit 6J, Floor 6, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N
3899765	Building 1 33 MILL Street	Unit 6J, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899766	Building 1 33 MILL Street	Unit 6J, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900138	Building 1 33 MILL Street	Unit 6J, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900591	Building 1 33 MILL Street	Unit 6K, Floor 6, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899767	Building 1 33 MILL Street	Unit 6K, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899768	Building 1 33 MILL Street	Unit 6K, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900139	Building 1 33 MILL Street	Unit 6K, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899769	Building 1 33 MILL Street	Unit 6L, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899770	Building 1 33 MILL Street	Unit 6L, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900140	Building 1 33 MILL Street	Unit 6L, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899771	Building 1 33 MILL Street	Unit 6M, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899772	Building 1 33 MILL Street	Unit 6M, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900141	Building 1 33 MILL Street	Unit 6M, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900592	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900598	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900594	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900596	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899774	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899773	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900142	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900599	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Workspace	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900597	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Workspace	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900593	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Workspace	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900595	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Workspace	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900600	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Bedroom-BR-1- remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900601	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Bedroom-BR-1- remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900602	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Bedroom-BR-1- remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900603	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Bedroom-BR-1- remove water damaged substrate before repair	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900604	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Entire Unit	Occupants shall place all garbage within receptacles provided to avoid unsanitary conditions [N.J.A.C. 5:10-5.4(a)]	N
3899775	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899776	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900143	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900606	Building 1 33 MILL Street	Unit 6Q, Floor 6, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899777	Building 1 33 MILL Street	Unit 6Q, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899778	Building 1 33 MILL Street	Unit 6Q, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900144	Building 1 33 MILL Street	Unit 6Q, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900605	Building 1 33 MILL Street	Unit 6Q, Floor 6, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3900608	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Bedroom-BR 1	Repair door frame so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900607	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Bedroom-BR 1	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3899782	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899781	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900146	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900610	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Entrance-entry way	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900609	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Entrance-entry way	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3899783	Building 1 33 MILL Street	Unit 6S, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899784	Building 1 33 MILL Street	Unit 6S, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900147	Building 1 33 MILL Street	Unit 6S, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900612	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900614	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900613	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900611	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3899786	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899785	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900148	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900617	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N
3900616	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3899787	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899788	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900149	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900615	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3899789	Building 1 33 MILL Street	Unit 6V, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899790	Building 1 33 MILL Street	Unit 6V, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900150	Building 1 33 MILL Street	Unit 6V, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900618	Building 1 33 MILL Street	Unit 6V, Floor 6, Building 1	Front Door	Repair apartment entry door(s) so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899791	Building 1 33 MILL Street	Unit 6W, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899792	Building 1 33 MILL Street	Unit 6W, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900151	Building 1 33 MILL Street	Unit 6W, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899793	Building 1 33 MILL Street	Unit 6X, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899794	Building 1 33 MILL Street	Unit 6X, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900152	Building 1 33 MILL Street	Unit 6X, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900619	Building 1 33 MILL Street	Unit 6X, Floor 6, Building 1	Front Door	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900621	Building 1 33 MILL Street	Unit 6Y, Floor 6, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899795	Building 1 33 MILL Street	Unit 6Y, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899796	Building 1 33 MILL Street	Unit 6Y, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900153	Building 1 33 MILL Street	Unit 6Y, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900620	Building 1 33 MILL Street	Unit 6Y, Floor 6, Building 1	Front Door	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3899797	Building 1 33 MILL Street	Unit 7A, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899798	Building 1 33 MILL Street	Unit 7A, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900154	Building 1 33 MILL Street	Unit 7A, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899800	Building 1 33 MILL Street	Unit 7B, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899799	Building 1 33 MILL Street	Unit 7B, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900155	Building 1 33 MILL Street	Unit 7B, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899803	Building 1 33 MILL Street	Unit 7C, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899804	Building 1 33 MILL Street	Unit 7C, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900157	Building 1 33 MILL Street	Unit 7C, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900630	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900626	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900622	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900628	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900624	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899805	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899806	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900158	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900625	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900623	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900627	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900629	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3899807	Building 1 33 MILL Street	Unit 7E, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899808	Building 1 33 MILL Street	Unit 7E, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900159	Building 1 33 MILL Street	Unit 7E, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900640	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900631	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900637	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900634	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900641	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900638	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900635	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900632	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900643	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N
3899810	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899809	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900160	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900636	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900642	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900633	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900639	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900646	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900647	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900645	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900644	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3899812	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899811	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900161	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900649	Building 1 33 MILL Street	Unit 7H, Floor 7, Building 1	Bathroom-repair tub drain/plug	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N
3900648	Building 1 33 MILL Street	Unit 7H, Floor 7, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899814	Building 1 33 MILL Street	Unit 7H, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899813	Building 1 33 MILL Street	Unit 7H, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900162	Building 1 33 MILL Street	Unit 7H, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900652	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N
3900651	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Bathroom	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N
3899815	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899816	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900163	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900650	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3900653	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Kitchen-stove/oven	Repair or replace cooking facility which is safely connected to a sufficient capacity electrical system or if gas connected to permanent fixtures and tubing to avoid the leakage of gas. *M [N.J.A.C. 5:10-20.1(a)6]	N
3900654	Building 1 33 MILL Street	Unit 7K, Floor 7, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N
3899817	Building 1 33 MILL Street	Unit 7K, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899818	Building 1 33 MILL Street	Unit 7K, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900164	Building 1 33 MILL Street	Unit 7K, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899819	Building 1 33 MILL Street	Unit 7L, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899820	Building 1 33 MILL Street	Unit 7L, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900165	Building 1 33 MILL Street	Unit 7L, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900655	Building 1 33 MILL Street	Unit 7M, Floor 7, Building 1	Bathroom	Repair or replace wash basin. *M [N.J.A.C. 5:10-21.1(e)1]	N
3899821	Building 1 33 MILL Street	Unit 7M, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899822	Building 1 33 MILL Street	Unit 7M, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900166	Building 1 33 MILL Street	Unit 7M, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899825	Building 1 33 MILL Street	Unit 7N, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899826	Building 1 33 MILL Street	Unit 7N, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900168	Building 1 33 MILL Street	Unit 7N, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899827	Building 1 33 MILL Street	Unit 7P, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899828	Building 1 33 MILL Street	Unit 7P, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900169	Building 1 33 MILL Street	Unit 7P, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900656	Building 1 33 MILL Street	Unit 7P, Floor 7, Building 1	Kitchen-exhaust fan	Occupant shall keep cooking equipment clean, free of garbage, food particles and grease. [N.J.A.C. 5:10-5.4(f)]	N
3900659	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Bedroom-BR 2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900660	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Bedroom-BR 2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900658	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Bedroom-BR 2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900657	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Bedroom-BR 2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3899829	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899830	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900170	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899831	Building 1 33 MILL Street	Unit 7R, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899832	Building 1 33 MILL Street	Unit 7R, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900171	Building 1 33 MILL Street	Unit 7R, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900661	Building 1 33 MILL Street	Unit 7S, Floor 7, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899834	Building 1 33 MILL Street	Unit 7S, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899833	Building 1 33 MILL Street	Unit 7S, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900172	Building 1 33 MILL Street	Unit 7S, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899836	Building 1 33 MILL Street	Unit 7T, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899835	Building 1 33 MILL Street	Unit 7T, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900173	Building 1 33 MILL Street	Unit 7T, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900662	Building 1 33 MILL Street	Unit 7T, Floor 7, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3899837	Building 1 33 MILL Street	Unit 7U, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899838	Building 1 33 MILL Street	Unit 7U, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900174	Building 1 33 MILL Street	Unit 7U, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899839	Building 1 33 MILL Street	Unit 7V, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899840	Building 1 33 MILL Street	Unit 7V, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900175	Building 1 33 MILL Street	Unit 7V, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899842	Building 1 33 MILL Street	Unit 7W, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899841	Building 1 33 MILL Street	Unit 7W, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900176	Building 1 33 MILL Street	Unit 7W, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900663	Building 1 33 MILL Street	Unit 7W, Floor 7, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3900668	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N
3900664	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900665	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900666	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900667	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3899843	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899844	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900177	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900669	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899847	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899848	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900179	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900670	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Hallway-closet doors	Repair door hardware so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900671	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Hallway-closet doors	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900672	Building 1 33 MILL Street	Unit 8A, Floor 8, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900673	Building 1 33 MILL Street	Unit 8A, Floor 8, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3899849	Building 1 33 MILL Street	Unit 8A, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899850	Building 1 33 MILL Street	Unit 8A, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900180	Building 1 33 MILL Street	Unit 8A, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899851	Building 1 33 MILL Street	Unit 8B, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899852	Building 1 33 MILL Street	Unit 8B, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900181	Building 1 33 MILL Street	Unit 8B, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899854	Building 1 33 MILL Street	Unit 8C, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899853	Building 1 33 MILL Street	Unit 8C, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900182	Building 1 33 MILL Street	Unit 8C, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900674	Building 1 33 MILL Street	Unit 8C, Floor 8, Building 1	Hallway-closet doors	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900676	Building 1 33 MILL Street	Unit 8D, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899856	Building 1 33 MILL Street	Unit 8D, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899855	Building 1 33 MILL Street	Unit 8D, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900183	Building 1 33 MILL Street	Unit 8D, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900675	Building 1 33 MILL Street	Unit 8D, Floor 8, Building 1	Kitchen	Repair or replace kitchen cabinets, cabinet doors or drawers to open and close properly. [N.J.A.C. 5:10-20.1(a)7]	N
3900677	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899858	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899857	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900184	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900678	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Hallway-closet door	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900680	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900679	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3899859	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899860	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900185	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900683	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Kitchen	Occupant shall keep cooking equipment clean, free of garbage, food particles and grease. [N.J.A.C. 5:10-5.4(f)]	N
3900681	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Kitchen	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900682	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Kitchen	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900684	Building 1 33 MILL Street	Unit 8G, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899862	Building 1 33 MILL Street	Unit 8G, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899861	Building 1 33 MILL Street	Unit 8G, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900186	Building 1 33 MILL Street	Unit 8G, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900687	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899864	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899863	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900187	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900686	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Hallway	REPAIR FLOOR COVERING to be free of hazards. [N.J.A.C. 5:10-8.2(a)]	N
3900685	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Living Room	REPAIR FLOOR COVERING to be free of hazards. [N.J.A.C. 5:10-8.2(a)]	N
3899865	Building 1 33 MILL Street	Unit 8J, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899866	Building 1 33 MILL Street	Unit 8J, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900188	Building 1 33 MILL Street	Unit 8J, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900688	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N
3900690	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Bathroom-repair tub drain/plug	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N
3900689	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900691	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Entire Unit	Eliminate Nuisance Oder which shall constitute a nuisance that is harmful or potentially harmful to the health and well-being of persons	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
				of ordinary sensitivity occupying or using the premises. [N.J.A.C. 5:10-6.2]	
3899869	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899870	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900190	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900693	Building 1 33 MILL Street	Unit 8L, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899871	Building 1 33 MILL Street	Unit 8L, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899872	Building 1 33 MILL Street	Unit 8L, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900191	Building 1 33 MILL Street	Unit 8L, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900692	Building 1 33 MILL Street	Unit 8L, Floor 8, Building 1	Kitchen	Repair or replace refrigerator to maintain temperatures between 32 and 50 degrees to avoid food spoilage. [N.J.A.C. 5:10-20.1(a)5]	N
3899874	Building 1 33 MILL Street	Unit 8M, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899873	Building 1 33 MILL Street	Unit 8M, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900192	Building 1 33 MILL Street	Unit 8M, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899876	Building 1 33 MILL Street	Unit 8N, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899875	Building 1 33 MILL Street	Unit 8N, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900193	Building 1 33 MILL Street	Unit 8N, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899878	Building 1 33 MILL Street	Unit 8P, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899877	Building 1 33 MILL Street	Unit 8P, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900194	Building 1 33 MILL Street	Unit 8P, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900694	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900696	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N
3899879	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899880	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900195	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900695	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Hallway	Provide Unrestricted Passage Thru Hallways. [N.J.A.C. 5:10-8.3(b)]	Y
3900697	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900698	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900699	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899882	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899881	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900196	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899883	Building 1 33 MILL Street	Unit 8S, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899884	Building 1 33 MILL Street	Unit 8S, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900197	Building 1 33 MILL Street	Unit 8S, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900702	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900701	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900700	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900703	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899886	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899885	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900198	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900704	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Kitchen-including faucets	Repair or replace kitchen sink. *M [N.J.A.C. 5:10-20.1(a)2]	N
3900706	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Bedroom-including above & beside windows	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900707	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Bedroom-including above & beside windows	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900708	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Bedroom-including above & beside windows	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900705	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Bedroom-including above & beside windows	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3899887	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899888	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900199	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900709	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom-BR1	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900711	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom-BR1	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900713	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom-BR1	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900715	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom-BR1	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900712	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom-BR2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900710	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom-BR2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900716	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom-BR2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900714	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom-BR2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899892	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899891	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900201	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899893	Building 1 33 MILL Street	Unit 8W, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899894	Building 1 33 MILL Street	Unit 8W, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900202	Building 1 33 MILL Street	Unit 8W, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899895	Building 1 33 MILL Street	Unit 8X, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899896	Building 1 33 MILL Street	Unit 8X, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900203	Building 1 33 MILL Street	Unit 8X, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899897	Building 1 33 MILL Street	Unit 8Y, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899898	Building 1 33 MILL Street	Unit 8Y, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900204	Building 1 33 MILL Street	Unit 8Y, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899899	Building 1 33 MILL Street	Unit 9A, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899900	Building 1 33 MILL Street	Unit 9A, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900205	Building 1 33 MILL Street	Unit 9A, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900717	Building 1 33 MILL Street	Unit 9B, Floor 9, Building 1	Bathroom	Repair or replace wash basin. *M [N.J.A.C. 5:10-21.1(e)1]	N
3900718	Building 1 33 MILL Street	Unit 9B, Floor 9, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899901	Building 1 33 MILL Street	Unit 9B, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899902	Building 1 33 MILL Street	Unit 9B, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900206	Building 1 33 MILL Street	Unit 9B, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900720	Building 1 33 MILL Street	Unit 9C, Floor 9, Building 1	Bathroom-repair tub drain/plug	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N
3900719	Building 1 33 MILL Street	Unit 9C, Floor 9, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899903	Building 1 33 MILL Street	Unit 9C, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899904	Building 1 33 MILL Street	Unit 9C, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900207	Building 1 33 MILL Street	Unit 9C, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899905	Building 1 33 MILL Street	Unit 9D, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899906	Building 1 33 MILL Street	Unit 9D, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900208	Building 1 33 MILL Street	Unit 9D, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900721	Building 1 33 MILL Street	Unit 9E, Floor 9, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899907	Building 1 33 MILL Street	Unit 9E, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899908	Building 1 33 MILL Street	Unit 9E, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900209	Building 1 33 MILL Street	Unit 9E, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899909	Building 1 33 MILL Street	Unit 9F, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899910	Building 1 33 MILL Street	Unit 9F, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900210	Building 1 33 MILL Street	Unit 9F, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900722	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900724	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900723	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900725	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3899914	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899913	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900212	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899915	Building 1 33 MILL Street	Unit 9H, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899916	Building 1 33 MILL Street	Unit 9H, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900213	Building 1 33 MILL Street	Unit 9H, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900726	Building 1 33 MILL Street	Unit 9J, Floor 9, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899917	Building 1 33 MILL Street	Unit 9J, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899918	Building 1 33 MILL Street	Unit 9J, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900214	Building 1 33 MILL Street	Unit 9J, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900727	Building 1 33 MILL Street	Unit 9J, Floor 9, Building 1	Kitchen-secure kitchen sink fuacet	Repair or replace faucet *M [N.J.A.C. 5:10-21.1(e)]	N
3899919	Building 1 33 MILL Street	Unit 9K, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899920	Building 1 33 MILL Street	Unit 9K, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900215	Building 1 33 MILL Street	Unit 9K, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899921	Building 1 33 MILL Street	Unit 9L, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899922	Building 1 33 MILL Street	Unit 9L, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900216	Building 1 33 MILL Street	Unit 9L, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900729	Building 1 33 MILL Street	Unit 9M, Floor 9, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899923	Building 1 33 MILL Street	Unit 9M, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899924	Building 1 33 MILL Street	Unit 9M, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900217	Building 1 33 MILL Street	Unit 9M, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900728	Building 1 33 MILL Street	Unit 9M, Floor 9, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3900730	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900736	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900733	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900737	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900731	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900734	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3899925	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899926	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900218	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900735	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Hallway	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900738	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Hallway	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900732	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Hallway	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900739	Building 1 33 MILL Street	Unit 9P, Floor 9, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899927	Building 1 33 MILL Street	Unit 9P, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899928	Building 1 33 MILL Street	Unit 9P, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900219	Building 1 33 MILL Street	Unit 9P, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900740	Building 1 33 MILL Street	Unit 9Q, Floor 9, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899929	Building 1 33 MILL Street	Unit 9Q, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899930	Building 1 33 MILL Street	Unit 9Q, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900220	Building 1 33 MILL Street	Unit 9Q, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899931	Building 1 33 MILL Street	Unit 9R, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899932	Building 1 33 MILL Street	Unit 9R, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900221	Building 1 33 MILL Street	Unit 9R, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900741	Building 1 33 MILL Street	Unit 9R, Floor 9, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y
3900742	Building 1 33 MILL Street	Unit 9S, Floor 9, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3899935	Building 1 33 MILL Street	Unit 9S, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899936	Building 1 33 MILL Street	Unit 9S, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900223	Building 1 33 MILL Street	Unit 9S, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900744	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Bathroom	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N
3900743	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3899937	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899938	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900224	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900746	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Living Room-@ sliding door	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900745	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Living Room-@ sliding door	Repair door frame so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3899940	Building 1 33 MILL Street	Unit 9U, Floor 9, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899939	Building 1 33 MILL Street	Unit 9U, Floor 9, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900225	Building 1 33 MILL Street	Unit 9U, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899942	Building 1 33 MILL Street	Unit 9V, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899941	Building 1 33 MILL Street	Unit 9V, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900226	Building 1 33 MILL Street	Unit 9V, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3899943	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899944	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900227	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900748	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900747	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900749	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900750	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3899945	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3899946	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3900228	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900759	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Front Door-repair lock so door can be readily opened	Repair door hardware so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900758	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Hallway	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900752	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Hallway	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900754	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Hallway	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900756	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Hallway	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900757	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900755	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900751	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900753	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900766	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N
3899948	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N
3899947	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/ fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y
3900229	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900764	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entrance	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900760	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entrance	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900762	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entrance	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900765	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Hallway	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900763	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Hallway	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900761	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Hallway	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900900	Building 2 33 MILL Street	Building Exterior 2 -	Entire Building	Relocate open-flame cooking device a minimum of 5 feet from combustible construction *M [N.J.A.C. 5:70-3.308(1)4]	Y
3900901	Building 2 33 MILL Street	Building Exterior 2 -	unit 24	Repair Patio Surface. [N.J.A.C. 5:10-6.4(a)4]	N
3900905	Building 2 33 MILL Street	Building Common 2 -	Garage	Interconnected common area smoke detection system shall be on circuitry that is connected into the building owner's electric meter. *P [N.J.A.C. 5:70-4.9(a)3i]	Y
3900903	Building 2 33 MILL Street	Building Common 2 -	Garage	Install AC powered constantly active electrical hard wired interconnected smoke detectors in all interior common areas, with the approval of the fire protection subcode official, fixed temperature or rate of rise combination heat detectors may be substituted for smoke detectors where frequent nuisance alarms would be likely to occur. *p [N.J.A.C. 5:70-4.9(a)3i]	Y
3900904	Building 2 33 MILL Street	Building Common 2 -	Laundry Room	Interconnected common area smoke detection system shall be on circuitry that is connected into the building owner's electric meter. *P [N.J.A.C. 5:70-4.9(a)3i]	Y
3900902	Building 2 33 MILL Street	Building Common 2 -	Laundry Room	Install AC powered constantly active electrical hard wired interconnected smoke detectors in all interior common areas, with the approval of the fire protection subcode official, fixed temperature or rate of rise combination heat detectors may be substituted for smoke detectors where frequent nuisance alarms would be likely to occur. *p [N.J.A.C. 5:70-4.9(a)3i]	Y
3900906	Building 2 33 MILL Street	Building Common 2 -	interconnect with laundry&garage	Repair exterior fire alarm bell *M [N.J.A.C. 5:70-3.907(8)1]	Y



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900881	Building 2 33 MILL Street	Unit 10, Floor 1, Building 2	Bathroom-1st flr bath	Repair or Replace light fixture *M [N.J.A.C. 5:10-13.3(c)]	N
3900882	Building 2 33 MILL Street	Unit 10, Floor 1, Building 2	Stairwell/Stairway	Repair or Replace light fixture *M [N.J.A.C. 5:10-13.3(c)]	N
3900884	Building 2 33 MILL Street	Unit 12, Floor 1, Building 2	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900883	Building 2 33 MILL Street	Unit 12, Floor 1, Building 2	Front Door	Provide for every unit of dwelling space in hotels and multiple dwellings some permanent and legible identification by letter, number or other symbol at or near the front entrance thereof [N.J.A.C. 5:10-18.2(a)]	N
3900886	Building 2 33 MILL Street	Unit 12, Floor 1, Building 2	Living Room	Eliminate Nuisance Oder which shall constitute a nuisance that is harmful or potentially harmful to the health and well-being of persons of ordinary sensitivity occupying or using the premises. [N.J.A.C. 5:10-6.2]	N
3900885	Building 2 33 MILL Street	Unit 12, Floor 1, Building 2	Living Room	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900887	Building 2 33 MILL Street	Unit 14, Floor 1, Building 2	Bathroom	Caulk bathtub/shower [N.J.A.C. 5:10-21.1(e)]	N
3900888	Building 2 33 MILL Street	Unit 16, Floor 1, Building 2	Bathroom	Caulk bathtub/shower [N.J.A.C. 5:10-21.1(e)]	N
3900889	Building 2 33 MILL Street	Unit 16, Floor 1, Building 2	Living Room-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900892	Building 2 33 MILL Street	Unit 16, Floor 1, Building 2	Living Room-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900891	Building 2 33 MILL Street	Unit 16, Floor 1, Building 2	Living Room-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900890	Building 2 33 MILL Street	Unit 16, Floor 1, Building 2	Living Room-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900894	Building 2 33 MILL Street	Unit 18, Floor 1, Building 2	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900893	Building 2 33 MILL Street	Unit 18, Floor 1, Building 2	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900872	Building 2 33 MILL Street	Unit 20, Floor 1, Building 2	Entire Unit	Provide admission to dwelling unit to conduct inspection. [N.J.A.C. 5:10-1.10(a)]	N
3900896	Building 2 33 MILL Street	Unit 24, Floor 1, Building 2	Dining Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900895	Building 2 33 MILL Street	Unit 24, Floor 1, Building 2	Dining Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900897	Building 2 33 MILL Street	Unit 24, Floor 1, Building 2	Stairwell/Stairway	Repair or Replace light fixture *M [N.J.A.C. 5:10-13.3(c)]	N
3900898	Building 2 33 MILL Street	Unit 26, Floor 1, Building 2	Hallway-1st flr hall	Repair or Replace light fixture *M [N.J.A.C. 5:10-13.3(c)]	N
3900899	Building 2 33 MILL Street	Unit 26, Floor 1, Building 2	Kitchen	REPAIR OR REPLACE KITCHEN VENTILATION EXHAUST SYSTEM TO EXHAUST AT LEAST 2 CUBIC FEET OF AIR PER MINUTE PER SQUARE FOOT OF FLOOR AREA DIRECTLY TO THE OUTSIDE. *M [N.J.A.C. 5:10-16.3(a)1]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900873	Building 2 33 MILL Street	Unit 4, Floor 1, Building 2	Entire Unit-provide records of extermination	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N
3900877	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Bedroom-middle bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900879	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Bedroom-middle bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900876	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Hallway-2nd flr hall	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900878	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Hallway-2nd flr hall	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900880	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Kitchen	REPAIR OR REPLACE KITCHEN VENTILATION EXHAUST SYSTEM TO EXHAUST AT LEAST 2 CUBIC FEET OF AIR PER MINUTE PER SQUARE FOOT OF FLOOR AREA DIRECTLY TO THE OUTSIDE. *M [N.J.A.C. 5:10-16.3(a)1]	N
3900875	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900874	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900962	Building 3 33 MILL Street	Building 3 - Exterior	Entire Building	Repair foundation wall to be free of cracks and holes. *M [N.J.A.C. 5:10-7.2]	N
3900964	Building 3 33 MILL Street	Building 3 - Exterior	Entire Building	Relocate open-flame cooking device a minimum of 5 feet from combustible construction *M [N.J.A.C. 5:70-3.308(1)4]	Y

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900963	Building 3 33 MILL Street	Building 3 - Exterior	near 30-34 & @ corner	Make leaders and drainpipes direct storm waters into draining systems and away from the foundation walls of the structure [N.J.A.C. 5:10-7.5]	N
3900961	Building 3 33 MILL Street	Building 3 - Common	Entire Building	Waterproof crawl space to prevent the penetration of Water or other Sources of Moisture. [N.J.A.C. 5:10-8.1(a)]	N
3900959	Building 3 33 MILL Street	Building 3 - Common	Utility Room- interconnect with exterior bell	Install AC powered constantly active electrical hard wired interconnected smoke detectors in all interior common areas, with the approval of the fire protection subcode official, fixed temperature or rate of rise combination heat detectors may be substituted for smoke detectors where frequent nuisance alarms would be likely to occur. *p [N.J.A.C. 5:70-4.9(a)3i]	Y
3900960	Building 3 33 MILL Street	Building 3 - Common	interconnect with utility room	Repair exterior fire alarm bell *M [N.J.A.C. 5:70-3.907(8)1]	Y
3900907	Building 3 33 MILL Street	Unit 28, Floor 1, Building 3	Entire Unit	Provide admission to dwelling unit to conduct inspection. [N.J.A.C. 5:10-1.10(a)]	N
3900910	Building 3 33 MILL Street	Unit 30, Floor 1, Building 3	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900911	Building 3 33 MILL Street	Unit 30, Floor 1, Building 3	Bedroom-master bedroom	Repair or replace electric outlet. [N.J.A.C. 5:10-13.1(b)7]	N
3900912	Building 3 33 MILL Street	Unit 30, Floor 1, Building 3	Entire Unit-cover baseboard units	Cover the heating system, including such parts as heating risers, ducts and hot water lines, with an insulating material or guard to protect occupants and other persons on the premises from receiving burns due to chance contact [N.J.A.C. 5:10-14.3(d)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900909	Building 3 33 MILL Street	Unit 30, Floor 1, Building 3	Kitchen	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900908	Building 3 33 MILL Street	Unit 30, Floor 1, Building 3	Living Room	Correct Inadequate Load Bearing to be Capable of Sustaining Safely Its Own Weight and Loads to Which they May be Subject To *M [N.J.A.C. 5:10-7.1]	Y
3900913	Building 3 33 MILL Street	Unit 32, Floor 1, Building 3	Bedroom-front bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900914	Building 3 33 MILL Street	Unit 32, Floor 1, Building 3	Bedroom-front bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900918	Building 3 33 MILL Street	Unit 34, Floor 1, Building 3	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N
3900917	Building 3 33 MILL Street	Unit 34, Floor 1, Building 3	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900916	Building 3 33 MILL Street	Unit 34, Floor 1, Building 3	Kitchen	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900915	Building 3 33 MILL Street	Unit 34, Floor 1, Building 3	Kitchen	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900919	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-1st flr	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N
3900921	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-1st flr	REPAIR OR REPLACE MECHANICAL BATHROOM VENTILATION TO EXHAUST AT LEAST 50 CUBIC FEET OF AIR PER MINUTE IN ROOMS WITH 1 TOILET OR URINAL DIRECTLY TO THE OUTSIDE *M [N.J.A.C. 5:10-16.3(a)3]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900923	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-2nd flr	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900922	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-2nd flr	REPAIR OR REPLACE MECHANICAL BATHROOM VENTILATION TO EXHAUST AT LEAST 50 CUBIC FEET OF AIR PER MINUTE IN ROOMS WITH 1 TOILET OR URINAL DIRECTLY TO THE OUTSIDE *M [N.J.A.C. 5:10-16.3(a)3]	N
3900920	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-2nd flr	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N
3900924	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-2nd flr	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900926	Building 3 33 MILL Street	Unit 38, Floor 1, Building 3	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N
3900925	Building 3 33 MILL Street	Unit 38, Floor 1, Building 3	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900927	Building 3 33 MILL Street	Unit 38, Floor 1, Building 3	Bathroom-2nd flr	REPAIR OR REPLACE MECHANICAL BATHROOM VENTILATION TO EXHAUST AT LEAST 50 CUBIC FEET OF AIR PER MINUTE IN ROOMS WITH 1 TOILET OR URINAL DIRECTLY TO THE OUTSIDE *M [N.J.A.C. 5:10-16.3(a)3]	N
3900933	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900928	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Front Door	Provide for every unit of dwelling space in hotels and multiple dwellings some permanent and legible identification by letter, number or other symbol at or near the front entrance thereof [N.J.A.C. 5:10-18.2(a)]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900932	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900931	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900929	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900930	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900939	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom-2nd flr	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900938	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom-2nd flr	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900936	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom-2nd flr	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900937	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom-2nd flr	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900935	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom-repair tub drain/plug	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900934	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N
3900940	Building 3 33 MILL Street	Unit 44, Floor 1, Building 3	Stairwell/Stairway-stair 1st to 2nd flr	Repair Steps to be Free of Hazards. [N.J.A.C. 5:10-6.4(a)4]	N

<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900941	Building 3 33 MILL Street	Unit 46, Floor 1, Building 3	Entire Unit	Provide admission to dwelling unit to conduct inspection. [N.J.A.C. 5:10-1.10(a)]	N
3900943	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N
3900942	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900946	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom-2nd flr	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900945	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom-2nd flr	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900944	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom-2nd flr	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900947	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom-2nd flr	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900955	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N
3900954	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom-2nd flr	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N
3900953	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom-2nd flr	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N
3900952	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom-2nd flr	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N



<b>Violation ID</b>	<b>Bldg #</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>
3900951	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom-2nd flr	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N
3900950	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom-repair sub floor before floor replacement	REPLACE FLOOR COVERING to be free of hazards. [N.J.A.C. 5:10-8.2(a)]	N
3900948	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Dining Room	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900949	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Kitchen	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N
3900957	Building 3 33 MILL Street	Unit 52, Floor 1, Building 3	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N
3900956	Building 3 33 MILL Street	Unit 52, Floor 1, Building 3	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N
3900958	Building 3 33 MILL Street	Unit 52, Floor 1, Building 3	Kitchen	REPAIR OR REPLACE KITCHEN VENTILATION EXHAUST SYSTEM TO EXHAUST AT LEAST 2 CUBIC FEET OF AIR PER MINUTE PER SQUARE FOOT OF FLOOR AREA DIRECTLY TO THE OUTSIDE. *M [N.J.A.C. 5:10-16.3(a)1]	N

### **UNITS/AREAS WITH NO VIOLATIONS**

<b>Bldg #</b>	<b>Area</b>
Building 2 33 MILL Street	Unit 2, Floor 1, Building 2
Building 2 33 MILL Street	Unit 6, Floor 1, Building 2
Building 2 33 MILL Street	Unit 22, Floor 1, Building 2

Bldg #	Area
Building 3 33 MILL Street	Unit 54, Floor 1, Building 3

**IMPORTANT NOTICE TO OWNERS**  
**(PLEASE READ CAREFULLY)**

IF YOUR BUILDING WAS BUILT BEFORE 1978 AND IT IS NOT CERTIFIED AS BEING LEAD FREE, ALL WORK PERFORMED TO ABATE PAINTING VIOLATIONS OR VIOLATIONS THAT DISTURB PAINTED SURFACES SHALL BE CARRIED OUT USING LEAD SAFE WORK PRACTICES BY INDIVIDUALS TRAINED IN ACCORDANCE WITH N.J.A.C.5:10-6.6(g). UPON REINSPECTION, THE PROPERTY OWNER MUST HAVE AVAILABLE FOR THE INSPECTORS REVIEW, ANY TRAINING RECORDS TO SUPPORT COMPLIANCE WITH N.J.A.C. 5:10-6.6(g), AS WELL AS ANY REQUIRED WIPE SAMPLES SHOWING THE WORK AREA TO BE LEAD HAZARD FREE. IF THERE IS DOCUMENTATION INDICATING THAT THE SURFACES CITED DO NOT CONTAIN LEAD BASED PAINT, THEN ALL WORK MUST COMPLY WITH N.J.A.C. 5:10-8.2.

**PERMIT INFORMATION (CORRECTIVE ACTION WITH THE FOLLOWING FOOTNOTE)**

'P' - A CONSTRUCTION PERMIT IS REQUIRED FROM THE CONSTRUCTION OFFICIAL. COPIES OF THE ISSUED CONSTRUCTION PERMITS AND THE CONSTRUCTION OFFICIAL'S APPROVALS OF WORK COMPLETED MUST BE PROMINENTLY DISPLAYED IN THE IMMEDIATE VICINITY OF THE WORK PERFORMED UNTIL THE BUREAU OF HOUSING INSPECTION HAS COMPLETED IT'S REINSPECTION.

'M' - A CONSTRUCTION PERMIT MAY OR MAY NOT BE REQUIRED CONTINGENT UPON THE EXTENT OF THE REQUIRED WORK TO ABATE THE CITED VIOLATION(S). COPIES OF THE ISSUED CONSTRUCTION PERMITS AND THE CONSTRUCTION OFFICIAL'S APPROVAL OF WORK MUST BE PROMINENTLY DISPLAYED IN THE IMMEDIATE VICINITY OF THE WORK PERFORMED UNTIL THE BUREAU OF HOUSING INSPECTION HAS COMPLETED ITS REINSPECTION.

**VIOLATIONS - REINSPECTIONS**

A reinspection will take place no earlier than 60 days from which this inspection report was delivered or served. If you have any questions, contact the Bureau at (609) 633-6225 or (609) 633- 6210.

**INSPECTION FEE PAYMENT**

The Order to Pay Inspection Fee , received with this report, must be returned with the fee (SPECIFIED ON INVOICE) within 90 days of the day it was delivered or served. Payments may be made online at the Division of Codes and Standards website ([www.nj.gov/dca/divisions/codes](http://www.nj.gov/dca/divisions/codes)) under the DCA RIMS Online Services link. You may also mail your payment, with the invoice stub, to State of New Jersey, DCA BHI - DORES, PO Box 662, Trenton, NJ 08646-0662. If payment is not received within 90 days, a penalty will be assessed in the amount of \$50.00 or 50% of the inspection fee, whichever is greater up to \$500.00 maximum.

The Certificate of Inspection cannot be issued until all violations have been corrected, all fees and penalties have been paid, and the Certificate of Registration has been issued to the current owner. If you have any questions, contact the Bureau at (609) 633-6225 or (609) 633-6210.

### **HEARING REQUEST**

You have the right to contest these orders at an administrative hearing. Requests may be submitted online at the Division of Codes and Standards website ([www.nj.gov/dca/divisions/codes/](http://www.nj.gov/dca/divisions/codes/)) under the DCA RIMS Online Services link. Click "Submit an Appeal Request". Requests **MUST BE MADE WITHIN 15 DAYS AFTER THESE ORDERS WERE DELIVERED AND SERVED.**

Requests not submitted online **MUST BE MADE IN WRITING AND MUST BE POSTMARKED WITHIN 15 DAYS AFTER THESE ORDERS WERE DELIVERED AND SERVED.** Requests must set forth in detail all issues, **FACTUAL, LEGAL or PROCEDURAL**, intended to be raised at the hearing as any issue not so raised shall be deemed waived. Please be sure to include, with your request, the property address, registration number, and reinspection date and mail to **HEARING COORDINATOR, BUREAU OF HOUSING INSPECTION, PO BOX 810, TRENTON, NJ 08625-0810.**

A corporation must be represented only by: (1) a licensed attorney; or (2) a person who submits a written statement bearing the corporate seal which specifies that, by means of corporate resolution, he/she has been authorized as corporate agent in this matter.

You will be notified of the time and place of the hearing which shall be held pursuant to Section 18 of the Hotel and Multiple Dwelling Law and the Administrative Procedures Act. If you have any questions, contact the Bureau of Housing Inspection Hearing Coordinator at (609) 633-6216.

### **EXTENSION REQUEST**

You may request an extension of time to correct any violation(s). By requesting an extension with respect to a violation, one expressly waives the right to a hearing as to that violation and concedes that the Inspection Report and Orders are correct and free from procedural or substantive defects as to that violation. While the extension request is being considered, the reinspection date on this inspection report, by which all violations must be corrected, does not change and remains the same for any violation for which an extension was denied.

Extension requests **MUST BE SUBMITTED TWO (2) WEEKS PRIOR TO THE REINSPECTION DATE ON THIS INSPECTION REPORT.**

Requests may be submitted online at the Division of Codes and Standards website ([www.nj.gov/dca/divisions/codes/](http://www.nj.gov/dca/divisions/codes/)) under the DCA RIMS Online Services link. Click "Request an Extension" under the Bureau of Housing Inspection.

Requests ***not*** submitted online must be made in writing and must state in detail: (1) the violations corrected to date; (2) the reason why each uncorrected violation cannot be corrected prior to the reinspection date on this inspection report; and (3) the date by which all violations will be corrected. Please be sure to include the property address, registration number and the reinspection date in your

request for an extension and mail to: BUREAU OF HOUSING INSPECTION (EXTENSIONS), PO BOX 810, TRENTON, NJ 08625-0810.

### **EXCEPTION REQUEST**

An owner may request an exception from an Order to correct any listed violation. A request for an exception **MUST BE MADE IN WRITING WITHIN 30 DAYS OF WHEN THE INSPECTION REPORT AND ORDERS WERE DELIVERED AND SERVED**. As provided by law, an exception can only be granted if: (1) compliance with the order would cause undue hardship (not purely financial hardship); and (2) an alternative means of correcting the violation exists which would not endanger the building occupants nor the public in general.

Please be sure to include the property address, registration number and the reinspection date in your request for the exception and mail to: BUREAU OF HOUSING INSPECTION (EXCEPTIONS), PO BOX 810, TRENTON, NJ 08625-0810.

### **REGULATIONS AND CODES**

Corrective Actions prefixed by "5:10-" on this Inspection Report and Orders of the Commissioner refer to violations cited pursuant to the Regulations for Maintenance of Hotels and Multiple Dwellings N.J.A.C. 5:10-1 et seq. These regulations along with the New Jersey Multiple Dwelling Law N.J.S.A 55:13A-1 et. seq. are available online at the Department of Community Affairs, Division of Codes and Standards, Bureau of Housing Inspection website at: <http://www.nj.gov/dca/divisions/codes/offices/housinginspection.html>.

Corrective Actions prefixed by "5:70-" refer to violations cited under the New Jersey Uniform Fire Code N.J.A.C. 5:70-1 et. seq., which is available online at the Department of Community Affairs, Division of Fire Safety's website at: <http://www.nj.gov/dca/divisions/dfs/codes>.